

SAMPLE CONTROLLED AUTOMATION CNC DATA.cad

XYZ-123 SAMPLE CNC DATA 203A 213 W 10 12 .1875 1
 .8125 0 RD 0 0 RD 0 0 RD 0 0 RD 0 0 RD 16
 1.5 3 01
 1.5 6 01
 49.5 3 01
 49.5 6 01
 53.5 3 01
 53.5 6 01
 104.5 3 01
 104.5 6 01
 108.5 3 01
 108.5 6 01
 159.5 3 01
 159.5 6 01
 163.5 3 01
 163.5 6 01
 211.5 3 01
 211.5 6 01

XYZ-123 SAMPLE CNC DATA 203B 138 W 10 12 .1875 1
 .8125 0 RD 0 0 RD 0 0 RD 0 0 RD 0 0 RD 12
 1.5 3 01
 1.5 6 01
 42.8125 3 01
 42.8125 6 01
 46.8125 3 01
 46.8125 6 01
 91.125 3 01
 91.125 6 01
 95.125 3 01
 95.125 6 01
 136.5 3 01
 136.5 6 01

XYZ-123 SAMPLE CNC DATA 203C 218.625 W 10 12 .1875 1
 .8125 0 RD 0 0 RD 0 0 RD 0 0 RD 0 0 RD 12
 52.3125 3 01
 52.3125 6 01
 56.3125 3 01
 56.3125 6 01
 107.3125 3 01
 107.3125 6 01
 111.3125 3 01
 111.3125 6 01
 162.3125 3 01
 162.3125 6 01
 166.3125 3 01
 166.3125 6 01

XYZ-123 SAMPLE CNC DATA 203D 143.625 W 10 12 .1875 1
 .8125 0 RD 0 0 RD 0 0 RD 0 0 RD 0 0 RD 8
 45.6875 3 01
 45.6875 6 01
 49.6875 3 01
 49.6875 6 01
 94 3 01
 94 6 01
 98 3 01
 98 6 01

XYZ-123 SAMPLE CNC DATA 203E 51.5 W 10 12 .1875 1
 0 0 RD 0 0 RD 0 0 RD 0 0 RD 0 0 RD 0

XYZ-123 SAMPLE CNC DATA 203F 51.5 W 10 12 .1875 1
 0 0 RD 0 0 RD 0 0 RD 0 0 RD 0 0 RD 0

XYZ-123 SAMPLE CNC DATA A2 5.5 L 3 3 .3125 16
 .8125 0 RD 0 0 RD 0 0 RD 0 0 RD 0 0 RD 2
 1.25 1.875 01
 4.25 1.875 01